Scope of Work for Property Located at:					2526 North Bremen Street							
	Property is:	Single Family	/	V	Dup	olex		Other □				
Date:	7/12/2016											
	ity for problems dis	scovered after the	e insp	ectio	on date	e, or f	or omission	ons through e	Redevelopment Aut Fror or oversight. Th rograms.			
Exterior Con	dition Repor	t										
Location Site	Required Wo	ork	n/a	V	Yes		Note/C	omments			\$	Cost
	Steps/Handrails		n/a	V	Yes				_		\$	
	Service walks		n/a		Yes	1					\$	1,500.00
	Fencing		n/a	4	Yes				_		\$	
	Parking		n/a	4	Yes				_		\$	
	Retaining walls		n/a	4	Yes				_		\$	
	Other		n/a		Yes				_		\$	
	Other		n/a		Yes				_		\$	
Garage	Singles: repair		n/a	7	Yes				_		\$	
	Shingles: Roof of	over existing	n/a	/	Yes						\$	
	Shingles:Tear of	ff & re-roof	n/a	√	Yes				_		\$	
	Gutters/downspo	outs	n/a		Yes	V			_		\$	756.00
	Flashing		n/a	V	Yes						\$	
	Eaves		n/a		Yes	V	repair fa	ascia			\$	756.00
	Siding		n/a	4	Yes						\$	
	Doors		n/a		Yes	1	service	door			\$	350.00
	Windows		n/a	4	Yes				-		\$	
	Slab		n/a	/	Yes						\$	
	Paint		n/a		Yes	1					\$	1,080.00
Porches	Electrical		n/a	V	Yes						\$	
	Other		n/a		Yes				_		\$	
	Roof		n/a	4	Yes		_				\$	
	Deck-upper		n/a	V	Yes		_				\$	-
	Decklower		n/a	√	Yes		_				\$	
	Steps/handrails		n/a	1	Yes						\$	
	Ceiling		n/a	1	Yes						\$	
	Guardrails		n/a	√	Yes						\$	
	Structural		n/a	V	Yes		_				\$	
	Paint		n/a	V	Yes		_				\$	

n/a Yes 🗸 skirting

100.00

Other

House

Chimney	n/a Yes 🗸	tuck pointing	\$ 300.00
Shingles: repair	n/a 🗸 Yes 🗌		\$
Shingles: Roof over existing	n/a 🗸 Yes 🗌		\$
Shingles:Tear off & re-roof	n/a ☑ Yes □		\$
Gutters/downspouts	n/a Yes 🗸		\$ 756.00
Flashing	n/a ☑ Yes 🗌		\$
Eaves	n/a ☑ Yes □		\$
Siding	n/a ☑ Yes □		\$
Storm Doors	n/a ☑ Yes □		\$
Prime ("main") Doors	n/a Yes 🗸		\$ 350.00
Storm Windows	n/a 🗸 Yes 🗌		\$
Prime ("main") Windows	n/a 🗸 Yes 🗌		\$
Paint	n/a ☐ Yes ✓		\$ 1,080.00
Foundation	n/a ☐ Yes ✓	repair brick on south side	\$ 800.00
Electrical	n/a ☑ Yes 🗌		\$
Other	n/a Yes		\$
Other	n/a Yes		\$
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$

Exterior: Estimated Cost:* \$ 7,828.00

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Cond	lition Report				
	Unit: Entire unit (single family)	7		Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work			Other	
-	Repair/replace boiler	n/a ☑	Yes 🗌	_	\$
	Repair radiation	n/a 🗸	Yes 🗌		\$
	Repair/replace furnace	n/a 🗸	Yes 🗌		\$
	Repair ductwork	n/a 🔽	Yes 🗌		\$
	Replace thermostat	n/a 🔽	Yes 🗌		\$
	Repair/replace grilles	n/a 🔽	Yes 🗌		\$
et	Tune boiler/furn. insp ht exchang	€n/a 🔽	Yes 🗌		\$
Electrical	Repair/replace receptacles	n/a 🗌	Yes 🗸	_	\$ 140.00
	Repair/replace switches	n/a 🗌	Yes 🗸		\$ 140.00
	Repair/replace fixtures	n/a 🔲	Yes 🗸		\$ 140.00
	Install outlets and circuits	n/a 🔽	Yes 🗌		\$
	Install outlets and circuits	n/a 🗸	Yes 🗌		\$
	Install outlets and circuits	n/a 🗸	Yes 🗌		\$
	Install outlets and circuits	n/a 🗸	Yes 🗌		\$
	Upgrade service	n/a 🗸	Yes 🗌		\$
	Other	n/a 🔲	Yes 🗸	misc basement electrical repairs	\$ 560.00
	Other	n/a 🗌	Yes 🗸	permit	\$ 85.00
Plumbing	Repair/replace kitchen sink	n/a 🗹	Yes 🗌		\$
	Repair/replace kitchen sink fauce	e n/a ☑	Yes 🗌		\$
	Repair/replace tub	n/a 🗸	Yes 🗌		\$
	Repair/replace tub faucet	n/a 🗌	Yes 🗸		\$ 390.00
	Repair/replace toilet	n/a 🗸	Yes 🗌		\$
	Repair/replace lavatory	n/a 🗸	Yes 🗌		\$
	Repair/replace lavatory faucet	n/a 🗸	Yes 🗌		\$
	Repair/replace wash tub	n/a 🗸	Yes 🗌		\$
	Repair/replace wash tub faucet	n/a 🗸	Yes 🗌		\$
	Unclog piping:	n/a 🗾	Yes 🗌	_	\$
	Repair drain/waste/vent piping	n/a 🗸	Yes 🗌		\$
	Repair water piping	n/a 🗸	Yes 🗌	36	\$
	Repair/replace water heater	n/a 🔲	Yes 🗸	missing overflow pipe	\$ 125.00
	Other	n/a 🗌	Yes 🗸	caulk tub/shower surround	\$ 34.00

\$

Other n/a Yes

Windows								
	Replace broken glass	n/a	√	Yes			\$	
	Repair or replace sash	n/a	1	Yes			\$	
Doors	Repair or replace doors	n/a	7	Yes		_	\$	
	Repair or repl. locks/latches	n/a	7	Yes		Self Help	\$	
Walls/Ceilings	Repair or repl. @ defective	n/a		Yes	7	misc drywall repairs	\$	960.00
Paint								
	Repair or repl. @ defective	n/a		Yes	4	_	\$	500.00
Fire Safety								
•	Install smoke/CO alarm:bsmt.	n/a		Yes	√	Self Help	\$	85.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	255.00
	Install smoke/CO alarm: 2nd flr.	n/a	4	Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a		Yes	7	Self Help	\$	248.00
Stairs	Repair defective	n/a	v	Yes	П		\$	
Floors								
Other	Repair defective	n/a	1	Yes			\$	
Other		n/a		Yes	4	patch hole in brick chimney in basement	\$	106.00
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	3,768.00
						Total Exterior and Interior Cost:*	\$	11,596.00
						*average contracted cost. Actual costs may vary. Self help will reduce the	amount.	

Self Help

Inspected by:

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Date: 7/12/2016

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Jeff Sporer

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.